

Spring Valley Lake Association Board Action/Information—Open Session

BAI 23/08/02

UV Filters					
Nicolas Gonzalez- Director of Operations					
August 8, 2023					
August 22, 2023					
123 Ponds	24 Lamp l	Cits & 16 Wiring Harnesses		\$15,910.36	
	_			\$15,947.28	
•	_			\$13,986.54	
Webb's Water Gardens	_			\$14, 727.57	
Imperial Sprinkler	All suppl	ies to change to 3" manifolds		\$203.80	
We recommend using The Pond Outlet					
The Pond Outlet offered the most competitive pricing for the equipment needed.					
N/A					
Amount on Reserve			\$40,00	\$40,000.00	
24 Lamp Kits and 16 Wiring Harnesses			\$13,98	\$13,986.54	
•					
				\$203.80	
10% Contingency			\$1,419	\$1,419.03	
<u>Total</u>			\$15,60	\$15,609.37	
Amount Remaining on Reserve		\$24,39	\$24,390.63		
Person Submitting: Nicolas Gonzalez General Manager: Alfred Logan					
	August 8, 2023 August 22, 2023 Our UV filters need new Additionally, we need to continue to the continue to	Nicolas Gonzalez- Director of Opera August 8, 2023 August 22, 2023 Our UV filters need new bulbs and wadditionally, we need to change the material sports and the second	Nicolas Gonzalez- Director of Operations August 8, 2023 August 22, 2023 Our UV filters need new bulbs and wiring harnesses as many of the bu Additionally, we need to change the manifolds to 3" manifold to preven 123 Ponds 24 Lamp Kits & 16 Wiring Harnesses Legendary Sale 24 Lamp Kits & 16 Wiring Harnesses The Pond Outlet 24 Lamp Kits & 16 Wiring Harnesses Webb's Water Gardens 24 Lamp Kits & 16 Wiring Harnesses Imperial Sprinkler All supplies to change to 3" manifolds We recommend using The Pond Outlet The Pond Outlet offered the most competitive pricing for the equipment N/A Amount on Reserve 24 Lamp Kits and 16 Wiring Harnesses *Includes tax and shipping All Supplies to change manifolds to 3" 10% Contingency Total Amount Remaining on Reserve	Nicolas Gonzalez- Director of Operations August 8, 2023 August 22, 2023 Our UV filters need new bulbs and wiring harnesses as many of the bulbs are no lo Additionally, we need to change the manifolds to 3" manifold to prevent them from 123 Ponds	